

SKU-0203

Products with 3D printing



The model is recommended as static



For good joining of parts, we recommend welding surfaces with solder and PLA filament.



version: black / gray




We recommend using a filler (BodyFill 360) that covers the print lines on the product. You can then sand the surface with sandpaper for a smooth surface. If the product is designed for a functional model in water, all surfaces of the product must be colored by the filler.

example


original surface




surface after use of the filler BodyFill360



Do not expose to direct sunlight.



The printing material is PLA. This is the same material as the RC models of aircraft. yet it is not recommended to leave it in the sun.



PE DESCRIPTION

TYPE XXI 1/72

