



SKU-0209

# Products with 3D printing



When melting, use a paper insulator as a protection.



brass pin

brass pin

filament PLA



For good joining of parts, we recommend welding surfaces with solder and PLA filament.



version: black / gray



We recommend using a filler (DodyFill 360) that covers the print lines on the product.


You can then sand the surface with sandpaper for a smooth surface.

If the product is designed for a functional model in water, all surfaces of the product must be colored by the filler.

## example

original surface

surface after use of the filler BodyFill360



small etched parts stick super glue

### Do not expose to direct sunlight.

The printing material is PLA. This is the same material as the RC models of aircraft. yet it is not recommended to leave it in the sun.

